

Alfra Rotabest Midi 50/50 Metal Core Drilling Machine



Operation Manual




1. Technical Data

Prod. – No.:	18615
Name :	Rotabest Midi 50/50
Input:	1200 Watt
No-Load rpm:	250/450 rpm
Tool Holder :	MT 2
Voltage:	(see nameplate)
Magnetic Adhesion:	16000 N
Boring Ø max. in Steel:	
- Core Cutter	50 mm
- Twist Drills	20 mm
Cutting Depth:	50 mm
Stroke:	170 mm
Size of Magnet Foot:	80 x 230 mm

2. Description

- a) Motor
- b) Spindle
- c) Control Panel
- d) Magnet Foot
- e) Arbor MT 3
- f) Depth Scale
- g) Hexagon screw for the adjustment of the motors' stroke range
- j) Recess for safety belt
- k) Adjusting screws for adjusting the slide



3. Standard scope of supply

- a) Transport Case
- b) Coolant Unit
- c) Coolant Spray
- d) Chip Remover
- e) Safety Belt
- f) Allan Key 2,5 mm
- g) Allan Key 6,0 mm
- h) Toolholder MT 2

Prior to use:



Read Operation Manual!



Pay attention to Safety Precautions!

Appropriate Use

This device is destined to:

Cut material with magnetizable surface with core cutters, twist drills and to tap threads in sheltered environment for commercial use industry and craft. The device is suitable for drilling vertical, horizontal and overhead.

4. Safety Precautions

Danger of Injuries

During drilling operations on walls and ceilings, the Metal Core Drilling Machine must be safeguarded with the included safety belt (f). **The magnetic adhesion is not maintained in case of a failure of circuit.**

The cut core will be ejected automatically by the ejector pin. **Danger of accident! The ejector pin could possibly break in case of improper use.**

Only use undamaged power cord and extension cords and regularly check on damages!

Power supply and voltage details at the device must correspond.

Personal protection equipment

When working with this device, wear the following protection equipment: Safety goggles, appropriate footwear, ear protection, hair net (for long hair), possibly also apron and safety helmet.

5. Precautions of use

The place of installation for the magnet foot must be clean and rustfree. Remove lacquer- and filler.
For non-magnetizable materials, please use the Rotabest Vacubest (Prod.- No. 18150).

Do not execute any electric welding on the workpiece, on which the Metal Core Drilling Machine is used.

Prior to all operations, mount coolant unit (b).

Danger of injuries! Danger of an electric shock

For operations on walls and ceilings, we recommend cooling with our spray (Alfra BIO 2000, Prod.- No. 21010).

Switching on and off.




- Check connecting line and plug on damages first!
- Push button MAGNET ON, in order to initiate the magnet and the magnetic adhesion is guaranteed.
- When working on walls and ceilings, safe machine with safety belt (f).
- Push the button MOTOR ON to start the Motor.
- The magnet foot now reaches its maximum magnetic adhesion! In case of a damaged magnet, the motor won't start.
- To switch off machine proceed in reverse order : MOTOR OFF and then MAGNET OFF!

Change of tools

How to work with annular cutters (Weldon shank)

- Mount Tool Holder AMK 2 in arbor.
- Push ejector pin (center pin) through head of annular cutter.
- Mounting of Rotabest Cutter according to drawing. Setscrew must be positioned in the center of the lateral flat side of the Weldon shank. Fix tightly.



How to work with twist drills.

- The drill chuck 3-16 mm with MT 2 shank is only to be used with twist drills.
- Insert drill chuck with adaptor in the arbor.
- Insert twist drill in drill chuck and tighten drill chuck key.
- Twist drills with MT 2 shank can be inserted directly into the arbor.

Tapping

With the Tapping Attachments it is possible to tap from M 3 up to M 16. The Tapping Attachment automatically switches over to left-hand rotation, as soon as spindle (B) is turned back.



Operating tips.

First, place annular cutter with ejector pin on a marked center or marking. Drilling with ALFRA Rotabest cutters does not require much expenditure of force. Set the cutter and spot-drill, until the entire cut edge is formed as a circle.

During the drilling process, the cutter should be cooled permanently. Optimal Cooling is possible by internal cooling with our coolant unit.

During the drilling process, do not stop the motor. After the process, cutter draw back with running motor.

Remove chips and core after each drilling. Remove chips with Chip-Remover – do not touch with bare hands – **DANGER OF INJURY!**

6. Cleaning.

Danger of injuries by unintentional switching on. Pull plug prior to cleaning.

Clean motor by means of dry compressed air (from the outside).

Check connecting lines on damages.

Clean and grease sliding surfaces regularly. Should, nevertheless, lateral play arise by wear of the dovetail guide, this could be adjusted by adjusting the laterally positioned set screws (K).

Carbon brushes should be replaced after appr. 250 hours running time.

After the work is finished, we recommend to store the Metal Core Drilling Machine in the transport case in a lying position.

7. Maintenance and repair.

Maintenance, check and repairs are only to be made by electronics specialists according to the valid regulations of the respective country.

The Metal Core Drilling Machine ALFRA ROTABEST should be serviced after appr. 250 hours running time by our Alfra workshop or appointed dealers.

Only use genuine ALFRA spare parts.

Spare part list at the end of this operation manual.

8. Accessories

	Alfra Rotabest HSS Co Eco Core Cutter Ø 12 – 50 mm Cutting depth 25 mm Product -No. 1901 0.. 025
	Center- and ejector pin Product –No. 1926500
	Alfra Rotabest HSS Co Eco Core Cutter Ø 12 – 50 mm Cutting depth 50 mm Product -No. 1901 0.. 050
	Center- and ejector pin Product –No. 1950500
	Alfra Rota Quick TCT Core Cutter Ø 18 – 35 mm Cutting Depth 35 mm Product -No. 2003 0.. 035
	Center- and ejector pin Product –No. 2001500
	Alfra Rota Quick TCT Core Cutter Ø 18 – 50 mm Cutting Depth 50 mm Product -No. 2003 0.. 050
	Center- and ejector pin Product –No. 2001501

	Alfra Tapping Attachment M3 – M12 Product-No. 18652 Alfra Tapping Attachment M10 – M 20 Product-No. 18653
	HSS Countersink and Deburrer Ø 25 mm Product -No. 18533 HSS Countersink and Deburrer Ø 40 mm Product -No. 18534
	Key Type Drill Chuck Ø 3-16 mm MT 2 Product -No. 18008
	Attachment for clamping pipes Product -No. 18019
	Vacuum device Vacubest Product -No. 18150
	Coolant unit Product -No. 18104
	Pressure Pump for coolant (5 Liter) Product -No. 20301
	Alfra Bio 2000 Cutting Oil Product -No. 21010
	Alfra Magnetic Chip Remover Product -No. 18654

9. Guarantee

For our ALFRA Rotabest Metal Core Drilling Machines we grant guarantee according to the legal and regional regulations (proven by invoice).

CE Declaration of Conformity

We declare in our exclusive responsibility, that this product correspond to the following standards and specifications:

**Specification 89/392/EWG, 91/368/EWG
DIN EN 292 part 1 and 2
DIN EN 60204 part 1
DIN VDE 0740 T**


The proof of an electromagnetic amiability took place according the appropriate EC-Specification 89/336/EWG after the following norms:

**EN 61000-3-2:1995/A1:1998/A2:1998
EN 61000-3-3:1995
EN 55014-1:1993/ A1:1997 55014-2:1997**

If the electric tool is modified without our authorization, this declaration will lose its validity and the guarantee expires.


The sound pressure level at the work place might exceed 85 dp(A). In case the user must wear hearing protectors.

10. Spare Parts



Pos.	N°	Stück	14	189480001	1	27	189100019	1	42	189491010	1
1	189501070	1	15	189301079	1	28	189112535	1	43	189411080 *	1
2	189501071	1	16	189501084	1	29	189490503	2	44	189501083	1
3	189411026 *	1	17	189120410	1	30	189301080	1	45	18104	1
5	189501072	1	18	189090410	5	31	189041210	3	46	18109.MK *	1
6	189501073	1	19	189040510	4	33	189601096	2	48	189060005	3
7	189501060	3	20	189020512	11	34	189480276	1	49	189060006	4
8	189501074	2	21	189040516	1	35	189490604	1	52	189490606	1
9	189480005	1	22	189030516A	1	36	189490605	2	53	189490607	1
10	189501076	1	23	189010650	4	37	189501079	1	55	189480020	1
11	189501077	1	24	189010880	1	39	189480009	1	56	189480021	1
12	189501078	1	26	189184816	4	40	189172050	8			

EHB 20/2.5



Item	Part-N°	Pce
1	189502070	1
2	189502071	4
3	189502052	1
3	189502052.110	1
4	189812011	1
5	189601017	1
6	189502053	2
7	189502054	2
8	189622009	4
9	189622010	4
10	189502072	1
11	189502011	1
12	189502057	1
13	189502073	4
14	189601018	1
15	189502058	1

16	189502074.B	1
17	189502066	1
18	189502018	1
19	189502019	1
20	189502020	1
21	189502021	1
24	189502078	1
25	189302020	1
32	189502032	1
33	189502033	1
34	189502034	1
35	189502035	1
36	189502036	1
37	189502037	1
38	189502038	1
39	189622055	1
40	189601020	1

42	189502061	1
43	189502043	2
44	189502062	1
44	189502062.110	1
45	189502076	1
48	189502065	1
49	189502067	1
50	189502068	1

11. Circuit diagram

