


MSW4 = MAST SEATED BATTERY DISCONNECT

SET PR1 TO GIVE 16.8V OUT WITH BATT DISCONNECTED

R2,3 = 10R CR50  
C1,2 = 1uF 63V Poly Box



VIEWED FROM SOCKET WIRING SIDE

