


## Parts Information:

## Air Conditioning Leak Detection Kit Model No: VS600.V2



Item	Part No.	Description
1	153.238F011	CABLE FASTENER & DOWEL
2	153.238T004	BULB SOCKET
3	153.238TD001	DICHROIC UV BULB, 50W, 12V, HALOGEN OSARM
4	153.304	PUSH BUTTON SWITCH
5	153.304	GLASS FILTER
6	153.3040001	CLAMP, RED
7	153.3040001	CLAMP, BLACK
8	153.3040001	O-RING SEAL
9	153.304007	SPRING

Item	Part No.	Description
10	153.3040002	SCREW
11	153.3040011	INJECTOR COMPLETE
12	153.3040002	GOGGLES
13	VS60012	AIR CON FLUORESCING LEAK DETECTION DYE 1
	VS60033	AIR CON FLUORESCING LEAK DETECTION DYE 3 (NOT SHOWN)
14	153.3040014	LAMP BODY, BLACK
15	153.3040014	LAMP COVER, GREY
17	153.304001	ROTATING COUPLING 6/4
18	153.304002	ROTATING COUPLING 4/6

NOTE: It is our policy to continually improve products and as such we reserve the right to alter data, specifications and component parts without prior notice. IMPORTANT: No liability is accepted for incorrect use of product.

WARRANTY: Guarantee is 12 months from purchase date, proof of which will be required for any claim.

Sealey Group, Kempson Way, Suffolk Business Park, Bury St Edmunds, Suffolk. IP32 7AR



01284 757500



01284 703534



sales@sealey.co.uk



www.sealey.co.uk

Page 1 of 1 VS600.V2 Issue 2 7/07/17